

A63365




Photo 5. Close-up of label stuck to case above keypad

At point 1.3 in Telstra's 12th December, 1994 (TF200 arbitration defence report), they state: "...The suspect TF200 telephone when received was found to be very dirty around the keypad with what appeared to be a sticky substance, possibly coffee."

The two photos on this page are allegedly of the same thing - they are both labelled "Photo 5. Close-up of label stuck to case above keypad". (I had put the label there to alert my staff that this was the phone to ring out of the holiday camp).

However, there is clearly a vast difference between these two photos. The very dark photo, above, labelled "A63365" is a Telstra Folio document of the same photo as shown below. The pale photo below was provided to me directly by Telstra's laboratory, and indentified as being the condition in which the TF200 EXICOM phone was presented in.

The overwhelming disparity between the two is highly suggestive of tampering, and the possible application of a sticky substance after the phone had been collected from my office.




Photo 5. Close-up of label stuck to case above keypad